



## 02.12.2014 Safety announcement Harness for paragliding

### Reference:

V-Line of the Charly rescue reserve light container Expert (see figure right)  
Affected are possibly all V-Lines that were purchased together with the rescue reserve light container Charly Expert



### Reason:

It has been ascertained that the strength of the webbing material used in the V-line delivered together with the Charly Expert light container differs from the tested sample.

**Urgency:** top priority

**Procedure:** All owners / users of the affected „Expert“ Light container are summoned to return the light container including the V-Line to the manufacturer for inspection and rectification. The inspection must be carried out BEFORE further use. The airworthiness is invalid until inspection by „Charly Produkte“ has been carried out.

**The inspection and replacement of the V-Line is free of charge**

**Finsterwalder GmbH – Charly Produkte**

Am Osterösch 3

D-87637 Seeg

Germany

**Phone:** +49 (0) 8364 / 1286

**Fax:** +49 (0) 8364 / 8426

**Mail:** [info@charly-produkte.de](mailto:info@charly-produkte.de)

[www.charly-produkte.de](http://www.charly-produkte.de)